



Practice Number: 5200295

<b>Equipment</b>	<b>UPS</b>	<b>Comply</b>	<b>Do not Comply</b>
<b>Business Unit</b>	OR Tambo and Chris Hani		
<b>Laboratory</b>	All Saints		
<b>Req. #</b>			

<b>Specification</b>	<b>Detail</b>		
Model	APS		
Capacity	2200 Last 48 hours		
Indicators	Green LED lighting, indicating load level		
Fault Alarm	Red LED lighting		
	Sounding every 2 seconds when in need of replacement		
Operating environment	Less noise, non-condensing		
	Installation of UPS		
<b>Lab manager</b>	T Stungu		
<b>Signature</b>			
<b>Date</b>	12-08-2020		
<b>QAC</b>	N. Dilinga		
<b>Signature</b>			
<b>Date</b>	12/08/2020		